



Vehicle Check Report

Standard inspection

1-VAN-456

Photos 4/4

Damages 1

DATE & TIME

07/07/2026 10:58

LICENSE PLATE

1-VAN-456

BRAND / MODEL / COLOUR

Mercedes-Benz Sprinter — White

ODOMETER

128400

FUEL LEVEL

6 / 8

Remarks

Vehicle in good overall condition. Minor scuff and shallow dent on the left sliding door noted at hand-over.



Vehicle photos

Front



Back



Left



Right





Damages

Dent · Minor — Left sliding door



Scuffed scrape with a shallow dent, lower panel.